

REQUEST FOR CORRECTIVE ACTION

<u>Request</u>	<u>Request</u>	<u>Model</u>	<u>Date</u>
T.Bach	CA-EU-02-22-10	P152	2022-07-09

Truck Model: P152,
Serial Number: P152L 0170 12020
0171
0172
0173
0175

Operating Hours: New

PROBLEM DESCRIPTION


The Overhead Guard (OHG) on the trucks show

1. Deformation





2. Poor surface and paint quality





3. Obvious areas of repaired paint



PROBLEM ROOT CAUSE

Training needed for the workers at the OHG manufacturing and painting facilities.

CORRECTIVE ACTION REQUIRED/SOLUTION

Quality assurance of OHG welding and painting needs to be improved.

Please send urgently 5 replacement OHGs in good quality. Rolf Eiten wishes to get these replacement OHG with air freight as soon as possible, as the customers are waiting for their trucks.